

Accessories

For all Height Gauges

1. Ruby Ball probe
Ø 1mm X 48mm Concentric
HEMR - BC - 0148



2. Ruby Ball probe
Ø 1.5mm X 48mm Concentric
HEMR - BC - 1548



3. Ruby Ball probe
Ø 2mm X 48mm Eccentric
HEMR - BE - 0248



4. Ruby Ball probe
Ø 2mm X 48mm Concentric
HEMR - BC - 0248



5. Ruby Ball probe
Ø 3mm X 48mm Concentric
HEMR - BC - 0348



6. Ruby Ball probe
Ø 3mm X 48mm Eccentric
HEMR - BE - 0348



7. Ruby Ball probe
Ø 3mm X 72mm Eccentric
HEMR - BE - 0372



8. Ruby Ball probe
Ø 3mm X 100mm Eccentric
HEMR - BE - 03A0



9. Ruby Ball probe
Ø 3mm X 100mm Concentric
HEMR - BC - 03A0



10. Ruby Ball probe
Ø 5mm X 48mm Eccentric
HEMR - BE - 0548



11. Ruby Ball probe
Ø 6mm X 48mm Eccentric
HEMR - BE - 0648



12. Carbide Ball probe
Ø 4mm X 48mm Eccentric
HEMC - BE - 0448



13. Carbide Ball probe
Ø 4mm X 72mm Eccentric
HEMR - BE - 0472



14. Carbide Ball probe
Ø 4mm X 72mm Concentric
HEMC - BC - 0472



15. Carbide Ball probe
Ø 4mm X 100mm Eccentric
HEMC - BE - 04A0



16. Carbide ball probe
Ø 6mm X 48mm Eccentric
HEMC - BE - 0648



17. Carbide ball probe
Ø 10mm X 48mm Concentric
HEMC - BC - 1048



18. Carbide ball probe
Ø 10mm X 100mm Concentric
HEMC - BC - 10A0



19. Disc probe
Ø 10mm X 48mm
HEMA - DC - 1048



20. Disc probe
Ø 20mm X 48mm
HEMA - DC - 2048



21. Carbide pin probe for groove
and thread Ø 1mm X 48mm
HEMC - GT - 0148



22. Carbide Pin probe for groove
and thread Ø 1.5mm X 48mm
HEMC - GT - 1548



23. Carbide Pin probe for groove
and thread Ø 2mm X 48mm
HEMC - GT - 0248



24. Depth probe 78mm
with replaceable insert
HEMA - DP - 0078



Accessory Box A
HEMA - 0A - 0000



Contains 3, 7, 11, 14, 17, 18

Accessory Box B
HEMA - 0B - 0000



Contains 1, 3, 6, 7, 8, 11,
12, 13, 14, 17, 18, 19

Accessory Box C
HEMA - 0C - 0000



Contains 1 - 19